

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

---

History of original corner establishment:

Index: X-20

Center east 1/16 corner Sec. 35, T.7S., R.31E., W.M.

Township originally subdivided by Frank Campbell under	1	DIAGRAM	1
Contract Number 380 in 1881.	1	T7SR31E	1
This corner was not set at that time.	1	1	1
	1	E --	1
	1	16	1
	1	C---.---C	1
	1	S35	1
	1	1993	1
	1	PLS852	1

Description of corner evidence found.  
None

Description of monument and accessories I established to perpetuate the original location of this corner:

The bearings were measured with a staff compass with a 20°E declination. I set a 2 1/2" x 30 " aluminum monument with 2 1/2" aluminum cap, marked as shown in the diagram, 20" in the ground with a collar of stone to 2" from the top.

I set the following witness trees:

A 12" dbh Ponderosa Pine bears N22 3/4°W, 30.0' scribed CE 1/16 S35 BT.

A 10" dbh Ponderosa Pine bears S68 3/4°E, 55.8' scribed CE 1/16 S35 BT.

An aluminum washer stamped RLS852 is nailed between the letters B and T on each new tree. All the BT's have LSM and BT signs attached. Painted 6" red bands around all the trees and painted the scribe blazes red.

This work was completed December 28, 1993.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*David L. Haddock*

**OREGON  
JULY 12, 1969  
DAVID L. HADDOCK  
852**

Office of Surveyor County of Grant  
 State of Oregon, I hereby certify that the within instrument was filed  
 in this office for record on the 14 day of Feb, 1994.  
Robert D. Bayliff by \_\_\_\_\_  
 ( COUNTY OFFICIAL ) ( DEPUTY )