


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Index: C-17
 Quarter corner, Secs. 2 and 3, T.7S., R.32E., W.M.
 Township originally subdivided by Rufus Moore under 1 DIAGRAM 1
 Contract No. 382 dated March 23, 1881. 1 BLM brass cap 1
 A retracement survey was made by 1
 the BLM under assignment instructions dated 1967. 1 1/4 1
 Their record reads: 1 S31S2 1
 The 1/4 sec. cor. of secs. 2 and 3, determined at 1 T79R32E 1
 record bearing and dist. from the remaining original 1 1967 1
 bearing tree: A tamarack stump, 28 ins. diam., bears 1
 S. 35°E., 15 lks. dist., mkd 1/4 S BT. At the corner 1
 point Set an iron post, 28 ins. long, 2 1/2 ins. diam. 1
 diam., 24 ins. in the ground, with brass cap mkd. (diagram) 1
 from which
 A white fir, 10 ins. diam., bears S. 80°E., 6 1/2 lks. dist., mkd.
 1/4 S2 BT. A white fir, 7 ins. diam., bears S. 46°W., 8 1/2 lks. dist.
 mkd. 1/4 S3 BT.

Description of corner evidence found:
 Found the corner monument as described from which:
 A 14" dbh White Fir bears S.80 1/2°E., 4.3' with healed blaze.
 A 11" dbh White Fir bears S.46°W., 5.6' with healed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:
 Set new bearing trees as follows:
 A 10" dbh White Fir bears N.42°E., 41.2' scribed 1/4 S2 BT.
 A 21" dbh Ponderosa Pine bears N.19 1/4°W., 111.7' scribed 1/4 S3 BT.
 The bearings were based on the record bearings to the existing BT's.
 An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. All the BT's have LSM and BT signs attached.
 Painted 6" red bands around all the trees and painted the scribe blazes red.

This work was done September 21, 1993.



Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed
 in this office for record on the 16th day of March, 1993.
Robert D. Bayett by _____
 (COUNTY OFFICIAL) (DEPUTY)