

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
 Quarter corner, Secs. 17 and 18, T.7S., R.32E., W.M.
 Township originally subdivided by Rufus Moore under
 Contract No. 382 dated March 23, 1881.

Index: L-5

A retracement survey was made by
 the BLM under assignment instructions dated 1967.
 Their record reads:

Point for the 1/4 sec. cor. of secs. 17 and 18,
 at proportionate distance; there is no remaining
 evidence of the corner. Set an iron post, 28 ins.
 long, 2 1/2 ins. diam., 24 ins. in the ground, in a
 collar of stone, with a brass cap mkd. (diagram).

1	DIAGRAM	1
1	BLM brass cap	1
1		
1	T79R32E	1
1	1/4	1
1	S18 S17	1
1	1968	1
1		1
1		1
1		1

from which

A fir, 23 ins. diam., bears N. 83 1/2°E., 49 1/2 lks. lks. dist., mkd.
 1/4 S17 BT. (1968)

A pine, 7 ins. diam., bears N. 16 1/2°W., 52 lks. lks. dist., mkd.
 1/4 S18 BT. (1968)

Description of corner evidence found:

Found the corner monument as described from which:

A 14" dbh Ponderosa Pine bears N.16 1/2°W., 34.3' with healed blaze.

A 26" dbh Douglas Fir bears N.83 1/2°E., 32.7' with healed blaze.

Description of monument and accessories I established to perpetuate the
 original location of this corner:

Set new bearing trees as follows:

A 10" dbh Western Larch bears S.71 1/2°W., 17.2' scribed 1/4 S18 BT.


A 7" dbh Ponderosa Pine bears S.38°E., 19.2' scribed 1/4 S17 BT.

The bearings were based on the record bearings to the existing BT's.


An aluminum washer stamped RLS 852 is nailed between the letters B and T
 on each new tree. All the BT's have LSM and BT signs attached.

Painted 6" red bands around all the trees and painted the
 scribe blazes red.

This work was done September 21, 1993.



David L. Haddock



Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed
 in this office for record on the 16 day of March, 1994.

Robert D. Bayett
 (COUNTY OFFICIAL)

by _____
 (DEPUTY)