

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index: CEW 1/64

C-E-W 1/64 corner, Sec. 28, T.7S., R.32E., W.M.		
Township originally subdivided by Frank Campbell under	1	DIAGRAM
Contract No. 380 dated 1881. This corner was not set	1	Al Cap
under that contract. A retracement survey was made by	1	T7SR32E
the BLM under assignment instructions dated 1967.	1	S28
This corner was not set at that time.	1	C-E-W
	1	.
	1	1/64
	1	1993
	1	PLS 852
	1	

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:


Set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap 26" in the ground with a 36" diameter collar of stone. Stamped the cap as shown in the diagram above, from which:

A 8" dbh Lodgepole Pine bears N20 1/4°E, 97.7' scribed CEW 1/64 BT.

A 10" dbh Western Larch bears S66 1/2°E, 45.5' scribed CEW 1/64 BT.

The bearings were measured with a staff compass with a declination of N20 E. An aluminum washer stamped RLS 852 is nailed between the letters B and T on each tree. All the BT's have LSM and BT signs attached. Painted 6" red bands around all the trees and painted the scribe blazes red.

This work was done September 24, 1993.



David L. Haddock



Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed
 in this office for record on the 21 day of Jan, 1994.
Robert D. Sigart by _____
 (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1286