


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.



Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2½" aluminum pipe with a 2½" aluminum cap stamped as shown in diagram.  
Set 2Ø" in the ground.

From which:

A Lodge-pole Pine 8" dia. bears S66°E, 8.7 ft. scribed SN 1/64 S34 BT.

A Fir 7" dia. bears S62°W, 28.4 ft. " " " S33 "

Set steel posts with warning sign and boundry signs South 4.0 ft. and East 5.0 ft.

Nailed brass washers stamped PLS848, bearing tree and warning signs to each tree.

Painted 6" red band around each tree.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

OREGON  
JULY 12, 1938  
DOUGLAS M. FERGUSON  
848

Corner monumented 8-29-83

Witnessed by Dan Martin

Office of..... Surveyor ..... County of..... Grant .....  
State of..... Oregon ....., I hereby certify that the within instrument was filed in this office  
for record on the..... 22 day of..... Nov ....., 19.. 83  
Robert D. Bayliss ..... by .....  
(COUNTY OFFICIAL) (DEPUTY)