


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.




Description of corner evidence found:

N/A

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 30"x2½" aluminum pipe with a 2½" aluminum cap stamped as shown in diagram.
 Set 14" in ground and raised a mound of stone around pipe.
 From which:
 A Fir 7" dia. bears N64°W, 48.5 ft. scribed NS 1/64 S33 BT.
 A Lodge-pole Pine 10" dia. bears S42°E, 10.0 ft. scribed NS 1/64 S34 BT.
 Set steel posts with warning and boundry signs North and East 5 ft.
 Nailed brass washers stamped PLS848, bearing tree and warning signs to each tree.
 Painted 6" red band around each tree.



Corner monumented 8-29-83

Witnessed by Dan Martin

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 22 day of Nov, 1983
Robert D. Boyer by _____
 (COUNTY OFFICIAL) (DEPUTY)

X 1/2 - 13