

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

**DIAGRAM**

T7S R35½E  
SE-SW  
1/64 S34  
1983  
PLS848

Description of corner evidence found:

N/A

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 30"x2½" aluminum pipe with a 2½" aluminum cap stamped as shown in diagram.  
Set 22" in the ground.

From which:

A Fir 10" dia. bears S86°W, 30.3 ft. scribed SE-SW 1/64 S34 BT.

A Lodge-pole Pine 7" dia. bears S60°E, 26.7 ft. scribed SE-SW 1/64 S34 BT.

Set steel post with warning signs North 5 ft. and East 8 ft.

Nailed brass washers stamped PLS848, bearing tree and warning signs to each tree.  
Painted 6" red band around each tree.

Corner monumented 8-30-83  
Witnessed by Dan Martin

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

Office of *Surveyor* County of *Grant*  
State of *Oregon*, I hereby certify that the within instrument was filed in this office  
for record on the *7<sup>th</sup>* day of *Nov*, 19*83*  
*Robert D. Boyett* by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)