


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 24 in. in the ground with a mound of earth to the cap, from which:

- A 9 in. dia. Lodgepole Pine bears S71½°E - 49.8 ft., scribed: S 1/16 S11 BT
- A 5 3/4 in. dia. Lodgepole Pine bears S7°W - 69.5 ft., scribed: S 1/16 S10 B

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set a steel fence post, with 54-2 and 54-9 signs attached, West of the monument, and post with sign 54-2 attached East of corner.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 27, 1983.

Witnessed by: Robert D. English  
Eric Giesler

Cap marked:

REGISTERED PROFESSIONAL LAND SURVEYOR
---

*William R. Wells*

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
---

T7S R35E
S 1/16
S10 • S11
1983
PLS 1106

Office of.....County Surveyor..... County of..... Grant  
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the...15...day of...Oct... , 1984  
*Robert D. English* by .....  
 (COUNTY OFFICIAL) (DEPUTY)