


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 15 in. in the ground with a mound of stone to the cap, from which:

A 6½ in. dia. Lodgepole Pine bears S72°E - 31.2 ft., scribed: CS1/16 S11 BT

A 8 in. dia. Lodgepole Pine bears S74°W - 15.0 ft., scribed: CS1/16 S11 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set steel fence posts (A) South of the monument with 54-2 and 54-9 signs attached, and (B) West of the monument with a 54-2 sign attached.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 27, 1983.


Witnessed by: Robert D. English
Eric Giesler

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Cap marked:



Office of... County Surveyor..... County of... Grant
State of... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the... 15... day of... Sept... 1983
Robert D. English by.....
(COUNTY OFFICIAL) (DEPUTY)