


CORNER RESTORATION

CORNER Angle Point TWP 8 S. RANGE 28 E.

ORIGINAL SURVEY BY: Aaron F. York; Retracement
Henry Meldrum
CONTRACT NUMBER: 309; 380
CONTRACT DATE: March, 1879; March, 1881



ORIGINAL DESCRIPTION: East on true line 40.00 chains set stone 18x16x8 for 1/4 corner (York).
Re-Survey by Henry Meldrum. NOTE: (Henry Meldrum found the South Boundary of Twp. 8 S., R. 28 E. very irregular and established new corners. However, he did not change the alignment of the standard parallel.) S. 87° 29' W. on South bndy. of Section 31; 40.00 chains set 14x11x8 in a mound of stone for 1/4 corner
51.96 chains found old 1/4 corner.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1983
ROBERT D. BAGETT
598

Bob Baggett
Chuck Ledford, Jr.

June 5, 1985

Grant County Surveyor.

EVIDENCE FOUND: Found stone 18x16x8 in fence line under rock jack, marked 1/4, set by Aaron York. This monument is an angle point on the Standard parallel.
SC

RECEIVED AND
FILED

JUN 19 1985

See Grant County Record Map of Survey No. 863.

OFFICE OF COUNTY SURVEYOR

Robert D. Baggett
Attest: *Carol Wright, Clerk*

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:
Show how trees are scribed and basis of bearings, including compass var.

I replaced marked stone with a 1 1/2"x30" iron pipe with attached brass cap set 30" in ground with cap marked as shown:
From which I set the following reference points:

- A 5/8" x 30" iron pin bears N. 35° E., 20.00 feet with yellow plastic cap marked B-G-A Survey Marker
- A 5/8" x 30" iron pin bears S. 50° E., 20.0 feet with yellow plastic cap marked B-G-A Survey Marker.

Buried original stone 1 foot South of pipe in bottom of hole.

Used magnetic compass with 20° E. var. and steel tape.

MONUMENT MARKED

