


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously set



Description of corner evidence found:

N.A.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 3"x30" galv iron pipe with 3" brass cap 16" in the ground, alongside a large boulder placed 2 other boulders alongside pipe & raised mound of stone & earth to fill the voids. Stamped brass cap as shown in diagram.

From which:

A pine 15" dia. bears N 52-40 W 29.2 ft. scribrd C W 1/16 S1 BT.

A pine 10" dia. bears S 12-30 E 45.5 ft. " " " " "

Nailed brass washers stamped PLS 848 & bearing tree signs to each tree. Painted red band around each tree. Set steel posts with warning & bdry. signs 5'S 5'W from corner. Bearing-solar grid

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Witness to above corner

D. Herburger

Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the *12* day of *Jan*, 19*81*.
Robert D. Bagert by _____
(COUNTY OFFICIAL) (DEPUTY)