


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

R-19

History of original corner establishment:

1881, F.W. Campbell, U.S. Deputy Surveyor, while subdividing the township under G.L.O. Contract No. 380 established the corner by setting a basalt stone 20 X 6 X 5 and raised mound of stone.


1979, William R. Wells, Registered Land Surveyor 1106, finding no evidence of the original corner set by proportion a 2" by 30" iron pipe, with brass cap, 18" in the ground and surrounded by mound of stones to the cap (Grant Co. Map of Survey No. 599), from which:  
10" Juniper, N 45° W, 81.2 feet.  
6" Juniper, S 35° E, 151.7 feet.



Description of corner evidence found:

Found a 2 1/2" iron pipe, with a 3" brass cap, projecting 16" out of the ground, surrounded by a rock mound 3 foot in diameter by 1 foot high, marked as shown, from which:

13" Juniper, S 23° E, 151.7 feet, with scribing "1/4 S26 BT" visible on partially healed blaze.  
15" Juniper, N 44° W, 81.2 feet, with scribing "1/4 S23 BT" visible on partially healed blaze with a 3/4" brass washer stamped "PLS 1106" nailed near the "BT" scribing.



Description of monument and accessories I established to perpetuate the original location of this corner:

New BT's:  
9" Juniper, N 44 1/2° E, 102.3 feet, scribed "1/4 S23" "BT".  
18" Juniper, S 64 1/2° W, 202.6 feet, scribed "1/4 S26" "BT".

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David A. Schlaich*

OREGON  
JULY 16, 1987  
DAVID A. SCHLAICH  
2308

RENEWAL DATE: 06/30/2000

Magnetic Declination 19° East

WORK PERFORMED BY: David A. Schlaich (RLS 2308)  
DATE: September 29, 1999

Office of... Surveyor ..... County of... Grant .....  
State of... Oregon ....., I hereby certify that the within instrument was filed in this office  
for record on the... 8... day of... Nov ....., 19... 99 .....  
Robert D. Baxter ..... by.....  
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1535

R-19