


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-13

History of original corner establishment:

The original corner was established by Aaron York under G.L.O. contract 309, dated July 12, 1879. His record reads:

Set Stone 46X18X3 for 1/4 Sec. Cor.
Raised Stone Mound at Cor.




set BT +, record BT x
PP=Ponderosa Pine
J =Juniper
DF=Douglas Fir
x----x fence
?=non-record BT

Description of corner evidence found:

Found no indication of corner stone or any stone mounds.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2" I.D. galvanized iron pipe 30" long with 2 1/2" brass cap stamped:
Set pipe 12" into the ground.



Placed a 3' diameter mound of stone around the monument and set a steel fence post 5' north of the monument with Forest Service Land Survey Monument and Property Boundary signs attached.

Scribed 1/4 S3 BT on a 6" Juniper which bears N85°35'E, 64.6'. Scribed 1/4 S4 BT on a 9" Juniper which bears N12°02'W, 6.8'. The bearings are true. Each scribe is in a 30" blaze. Nailed an aluminum washer, stamped RLS 852, between the letters B and T on each tree. Painted a 6" red band around the new bearing trees and attached Forest Service Land Survey Monument and Bearing Tree signs.

I certify the above corner point was proportioned as hereon described on August 12, 1987.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1968
DAVID L. HADDOCK
852

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of Oct, 1987
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)