


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



Description of corner evidence found:  
N.A.

Description of monument and accessories | established to perpetuate the  
original location of this corner:

Set 3"x30" galv iron pipe with 3" brass cap 6" in the ground & raised a large mound of stone  
around the pipe. Stamped the brass cap as shown in the diagram.  
From which  
A steel post with warning, bdry. & bearing signs bears south 6.0 ft.  
A steel post with bdry. & bearing tree signs bears west 6.6 ft.  
No bearing trees available.

Witnesses to above corner.

D. Herburger  
L. Wyllie

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1968  
DOUGLAS M. FERGUSON  
848

Office of... *Surveyor* ..... County of... *Grant* .....  
State of... *Oregon* ..... I hereby certify that the within instrument was filed in this office  
for record on the... *17* day of... *Jan* ..... 19... *81*  
*Robert O. Bager* by .....  
(COUNTY OFFICIAL) (DEPUTY)