


History of original corner establishment: Corner established in 1881 by Meldrum & Campbell under General Land Office Contract No. 380.

Surveyor General records state:

Set a basalt stone 18x15x8 & dug pits per ints. cor. secs. 1,12,6,7;

A Fir, 12 in. dia., bears S30°E, 20 lks. dist.,
" Pine 10 " " " S71°W, 49 " "



Description of corner evidence found:

Found a stone of the proper dimensions. Did not find chisel marks on stone. The original fir BT to the SE is a broken off stump about 5' high with legible scribing. The pine BT is very healthy and has grown considerably since it was scribed.

Description of monument and accessories established to perpetuate the

original location of this corner Set a 2"x30" galvanized pipe with flared end and 2 1/2" brass cap 24" in the ground. Made a rock mound around monument 6" high and 36" in diameter. Set a 4"x4"x6" redwood post 18" in the ground 3' West of monument with sign 54-4 as a guard post for the corner. Scalped bark and painted red band around Bearing Trees and posted signs 54-3 with the following information:

| | | | | | |
|-----|-------------|-------|-------|--|--|
| New | 20" P. Pine | N72°E | 32.4' | New BT's were scribed in upper blazes; T8S R31E S1 T8S R32E S6 T8S R32E S7 | and in lower blazes; BT, along with a brass nail & washer stamped RLS 699 |
| | 8" D. fir | S69°E | 37.1' | | |
| | 26" D. fir | S26°W | 48.7' | | |
| | 28" P. Pine | N62°W | 28.7' | | |
| | D. fir Stub | N30°W | 13.2' | | |

REGISTERED
PROFESSIONAL
LAND SURVEYOR


Leland Lee Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

I hereby certify the above corner monument was re-established as herein described on August 29, 1974.

74852

Office of *County Clerk* County of *Grant*
State of *Oregon* I hereby certify that the within instrument was filed in this office
for record on the *19* day of *Nov* 1974 *9050 Min Book 1, Page 214*
J. D. ... by *Deputy Surveyor*
(COUNTY OFFICIAL) (DEPUTY)



INDEXED