


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner originally established in 1881 by F.W. Campbell under general land office contract No. 380.
Surveyor general records state:
Set basalt stone 14x7x8 and dug pits as per inst. for 1/4 sec corner.



Description of corner evidence found:

No evidence found. It is doubtful that this corner was ever set as it falls in a rocky area where pits as called in the notes would be nearly impossible to dig & a stone mound would have been easily constructed.
No bearing trees where originally taken, there are some old trees in the area that could have been scribed. Therefor the corner position is established by proportion.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 3"x30" galv iron pipe with 3" brass cap 12" in ground & raised a mound of stone & earth around pipe. Stamped brass cap as shown in diagram.
From which: *DF*
A pine 9" dia bears N 33 E 10.1 ft. scribed 1/4 S18 BT.
A " 16" " *S72°W* S 15.8 ft. " " S13 "
Nailed brass washers stamped PLS848 & bearing tree signs to each tree, painted red band around each tree. Set steel post with warning sign 5'N from corner.
Bearing-True Grid

Witnesses to above corner.

D. Herburger
L. Wyllie

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Office of *Surveyor* County of *Grant*
State of *Oregon*, I hereby certify that the within instrument was filed in this office
for record on the *12* day of *Jan*, 198*1*
Robert D. Bisset by _____
(COUNTY OFFICIAL) (DEPUTY)