CERTIFIED RECORD OF LAND CORNER MONUMENTATION

J-02.06

History of original corner establishment:

NONE:

DIAGRAM

U.S. DEPT. OF AGRICULTURE
T8S R34E
S7
NFJD S18
AP-3256
RLS 2308
1995
FOREST SERVICE

Description of corner evidence found:

NONE:

Description of monument and accessories I established to perpetuate the original location of this corner:

SET IN A SMALL CREEK ON THE SECTION LINE BETWEEN SECTIONS 7 & 18, A 5/8" BY 24" REBAR, WITH A 3 1/4" ALUMINUM CAP, 20" IN THE GROUND, MARKED AS SHOWN (SEE DIAGRAM), FROM WHICH:

23" WESTERN LARCH, N. 57 1/4° E., 44.8 FEET, SCRIBED "WB/3256""BT".
17" WESTERN LARCH, N. 22° W., 33.9 FEET, SCRIBED "WB/3256""BT".

THE BT'S ARE DOUBLE BLAZED AND HAVE A 3/4" BRASS WASHER STAMPED "RLS 2308" NAILED TO THE LOWER BLAZE BETWEEN THE "BT" SCRIBING.

NAD83(1991)
LATITUDE: 44°52'52.06447" NORTH
LONGITUDE: 118°40'18.25149" WEST

MAGNETIC DECLINATION: 20° EAST

WORKED PERFORMED BY: DAVID A. SCHLAICH
WITNESSED BY: RACHELLEL (SHELLY) FLETCHER
DATE: AUGUST 28, 1995

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A Schlaich

OREGON
JULY 16, 1987
DAVID A. SCHLAICH
2308

RENEWS 06/30/96

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 6 day of Oct, 19 95
Robert D Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

See Map & Survey 1383 J-02.06