

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by W. B. Barr, Deputy Surveyor General, during the original survey. Contract No. 492 dated April, 1884.

Set Basalt Stone 12x8x8 ins 8 ins in the ground for cor. to Secs. 2, 3, 10 and 11 marked with 2 notches on E and 5 notches on S edges from which

raised a mound of stone in Sec. 3.

A Pine 8 ins. diam. bears N75°E, (138.6')210 lks. dist. marked TBSR35¹/₂E S2 BT

A Pine 18 ins. diam. bears S85°E, (142.6')216 lks. dist. marked TBSR35¹/₂E S11 BT

A Pine 18 ins. diam. bears S20°W, xxx lks. dist. marked TBSR35¹/₂E S10 BT

DIAGRAM

TBS R35¹/₂E

S 3 | S 2
S10 | S11

1983
RLS 699

Corner was monumented by James H. Hambleton, 645, during a retracement survey dated June, 1968, and an amending survey dated July, 1977.

Found stone and bearing trees to be in satisfactory shape.

Set a one inch iron pipe with aluminum cap stamped as per diagram (except year was 1968 and surveyor number was 645).

Description of corner evidence found:

1" galvanized unflared pipe .7" from the original stone.

16" Lodgepole pine (Dead)(Scribing Visible)(1884 BT) bears N72° 45'E, 140.4 feet.

Lodgepole pine (Down & Rotting Away)(Scribing Visible)(1884 BT) bears S89° 45'E, 143.1 feet.

Ponderosa pine (Rotted Off And Leaning Against Dead Tree)(Scribing Visible)(1884 BT) bears S23°45'W, 141.1 feet. Not able to read the distance from the original notes.

Mound of stone in Section 3.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 24 in the ground, replacing the pipe at the rock location which is turned upside down and buried on the north side of the monument.

Incorporated the old mound into a mound of rock to be 24" in diameter by 6 high around the monument, from which new BTs are:

7" Lodgepole pine bears S13° 30'W, 193.0 feet scribed TBSR35¹/₂E S10 BT

6" Lodgepole pine bears S68°30'E, 175.4 feet scribed S11 BT (due to small size, limited scribing)

15 Lodgepole pine bears N63° 15'E, 244.9 feet scribed TBSR35¹/₂E S2 BT

No tree in Section 3 within allowable limits.

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to the scribed blazes which were painted red. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet E of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on November 6, 1983, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 16 DAY OF OCT, 1985

Robert D. Beyer Co. Sur.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers
OREGON
JULY 9, 1965
LELAND LEE MYERS
699

See MAP OF SURVEY NO. 894