

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by Herman D. Gradon under GLO contract No. 499 dated March 11, 1884.

Surveyor's General records state:

Set a post 3 ft. long 3 ins. square 24 ins. in the ground for 1/4 sec cor marked 1/4 S on N face, from which:

- A fir 5 ins. diam. bears N 30° W, 22 lks. dist. marked 1/4 S BT
- A fir 7 ins. diam. bears S 75° E, 14 lks. dist. marked 1/4 S BT



Description of corner evidence found:

A fir 20 ins. diam. with healed blaze for section 24 BT

At the corner location as determined by the section 24 bearing tree found the rotten remains of a wooden post to a depth of 20 ins.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ in. brass cap on a 2 in. iron pipe 31 ins. long 26 ins. in the ground with a surrounding rock mound.

Brass cap marked thus: T 8 S R 35 E

$\frac{1}{4}$	$\frac{S\ 13}{S\ 24}$
---------------	-----------------------

1979

ORLS 1639

New bearing tree:

A tamarack 18 ins. diam. bears N 21° E, 56.0 ft. dist. marked 1/4 S 13 BT

I hereby certify the above corner monument was properly re-established under my supervision on Sept. 24, 1979 and witnessed by John Mitchell and Don Pedracini.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 5 day of Oct, 1979
Robert Baggett by _____
 (COUNTY OFFICIAL) (DEPUTY)

* SEE GRIFFITH 10/87