


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position, determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 27" in ground with raised mound of stone marked:
From Which:

A Pond. Pine 14" dia. bears N 4°E 23.9 ft. marked CNNSW 1/256	T8S R35E
S27 BT.	C-N-N-SW 1/256
A Pond. Pine 12" dia. bears S 76°W 28.1 ft. marked CNNSW 1/256	
S27 BT.	S27
	PLS 1099
	1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner perpetuated in accordance with Umatilla N.F. survey contract no. 53-04R3-2-01275.

20°E Declination
Steel Tape

Post South with 54-2 & 54-9
Post West with 54-2

Corner falls 200'+ North of main road on South face of hill.
September 1, 1983

Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Refer to Grant County Survey No. 828

Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Aug, 1984
Robert D. Dwyer by _____
(COUNTY OFFICIAL) (DEPUTY)

