


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At the intersection point, of a line 200 foot southerly of and perpendicular to the ordinary high water line on the south bank of Granite creek, with the N-S Centerline of the SE 1/4 of section 28, T. 8 S., R. 35 E., I set a 2 1/2" X 30" aluminum pipe, with 3 1/4" aluminum cap, 18" in the ground and placed rock mound around the monument, from which;

A 7" Lodgepole Pine, bears N 44 1/4 W, 2.6 feet, mkd. "WB/2249""BT".
A 6" Lodgepole Pine, bears S 49 3/4 W, 7.1 feet, mkd. "WB/2249""BT".
The C-S-N-SE 1/256 of section 28, which is a 2 1/2" iron pipe with brass cap projecting 2" out a stone mound, established in 1983 by Gary L. Langlitz (L.S. 1099), bears S 0-39-32 W, 21.44 feet.

BT's are double blazed and have a brass washer marked "RLS 2308" nailed to the lower blaze by the "BT" scribing.

Magnetic Declination: 20 degrees East.

Work performed by: David A. Schlaich (RLS 2308)
Witnessed by: Darron Trowbridge
Date: August 27, 1992

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A. Schlaich

OREGON
JULY 16, 1987
DAVID A. SCHLAICH
2308

EXPIRES 12/31/94

Office of... Surveyor County of... Grant
State of... Oregon I hereby certify that the within instrument was filed in this office
for record on the... 4 day of... June 19... 93
Robert D. Boyer by
(COUNTY OFFICIAL) (DEPUTY)