


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None


Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap in ground marked:

From which:

A Lodge Pole Pine 8" dia. bears N 32°E, 12.6 ft. marked C-SENW 1/256 S35 BT.

A Lodge Pole Pine 7" dia. bears N 32°W, 8.6 ft. marked C-SENW 1/256 S35 BT.



Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey contract no. 53-04R3-2-01275.

Post North w/54-2
 Post East w/54-2 & 54-9

20° E Declination Steel Tape

Corner in Lodge Pole Patch 300' from meadow 100' West of draw 2 cabins 250 west of corner.

September 21, 1983

Witnesses: A. Ray Crapo
 Greg Orton
 Kyle McKinney

Refer to Grant County Survey No. 828

Office of.....SURVEYOR..... County of.....GRANT.....
 State of.....OREGON....., I hereby certify that the within instrument was filed in this office
 for record on the.....30..... day of.....Aug....., 19.....83
 ..Robert D. Bayne..... by ..Gary L. Langlitz.....
 (COUNTY OFFICIAL) (DEPUTY)

