


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Found unrecorded pin
15.6 ft. North
14.0 ft. East

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 22" in the ground with raised mound of stone marked: T8S R35E
 From which: C-N-SW-NE 1/256
 A Lodgepole Pine 6" dia. bears N 23°W 18.8 ft marked X BT. +
 A Tamarack 12" dia. bears S 83°W 76.6 ft. marked CNSWNE 1/256 S35 BT. S35
 Attached brass washers stamped LS 1099 to BT blaze on both trees. PLS 1099
 1983

Corner location perpetuated in accordance with Umatilla N.F. survey No. 53-04R3-2-01275.

Post 5'+ West w/54-2
Post 5'+ South w/54-2 & 54-9

20° E Declination
Steel Tape

Corner falls in fence corner South edge of meadow.

September 12, 1983 Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Refer to Grant County Survey No. 828



Office of... SURVEYOR ... County of... GRANT ...
 State of... OREGON ... I hereby certify that the within instrument was filed in this office
 for record on the 30 day of AUG ... 1984
Robert D. Sajt by
 (COUNTY OFFICIAL) (DEPUTY)