


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

32

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 20" in the ground with raised mound of stone marked: T8S R35E  
 From which: S27  
 A Spruce 14" dia. bears S 15°E, 163.5 ft. marked SWSE 1/64 S27 BT. SW-SE  
 A Douglas Fir 12" dia. bears N 42°E, 104.8 ft. marked SWSE 1/64 S27  
 BT. ───┬───  
 1/64  
 PLS 1099  
 1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. Survey contract No. 53-04R3-2-01275.

Post 5'+ South with 54-2 & 54-9  
 Post 5'+ West with 54-2


20°E. Declination  
 Steel Tape

August 30, 1983

Witnesses: A. Ray Crapo  
 Greg Orton  
 Kyle McKinney

Corner position in draw 25' South of Meadow Edge.

Refer to Grant County Survey No. 828



Office of.....SURVEYOR..... County of.....GRANT.....  
 State of.....OREGON....., I hereby certify that the within instrument was filed in this office  
 for record on the 30 day of.....AUG....., 1984  
 Robert D. Bayne by.....  
 (COUNTY OFFICIAL) (DEPUTY)

U 1/2 - 15 1/2