


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position determined by survey set 2 1/2"x30" galv. iron pipe with brass cap 25" in ground with stone mound marked:

From which:

A White Fir 8" dia. bears N 46°W, 4.5 ft. marked SW NE 1/64

S35 BT.

A Tamarack 8" dia. bears S 37°W, 15.1 ft. marked SWNE 1/64 S35 BT.

T8S R35E
SW-NE 1/64

+

S35
PLS 1099
1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey No. 53-04R3-2-01275.

Post North w/54-2

Post East w/54-2 & 54-9

20°E Declination Steel Tape

Corner falls on North slope 50+ South of fence cor.
September 13, 1983

Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Refer to Grant County Survey No. 828



Office of.....SURVEYOR..... County of.....GRANT.....
 State of...OREGON... I hereby certify that the within instrument was filed in this office
 for record on the...30... day of...AUG... 19...84...
Robert W. Dwyer by.....
 (COUNTY OFFICIAL) (DEPUTY)