

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U-18

History of original corner establishment:

None, corner established this survey.

DIAGRAM

T8S R35E
SW 1/16 S26
1996
PLS 1106

Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey set a 2½" diameter aluminum pipe 30" long with a 2½" aluminum cap, marked as shown in corner diagram, projecting 3" out of a surrounding mound of stone.

Set steel fence post alongside with signs 54-2 and 54-9 attached.

New Bearing Trees:

A 9" diameter lodgepole pine bears N 06° E, 39.6 feet marked "SW1/16S26BT" on double blaze.

A 9½" diameter lodgepole pine bears S 73° E, 13.1 feet marked "SW1/16S26BT" on double blaze.

Each bearing tree has signs 54-3 and 54-9 attached below a 6" band of red paint. Each blaze painted with red paint and has a brass washer stamped "PLS 1106" attached.

Compass declintion 18° East.

Witnessed by: William L. Hanley
Kelly Snively

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Willi R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Renews 6/30/98

Office of... SURVEYOR County of... GRANT
State of... OREGON I hereby certify that the within instrument was filed in this office
for record on the... 18 day of... DEC 19... 96
Robert D. Bayne by
(COUNTY OFFICIAL) (DEPUTY)