


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None


Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 26" in the ground with raised mound of stone marked: T8S R35E

From which:

A Lodge Pole Pine 8" dia. bears S 8°E 19.6 ft. marked CNNW 1/64 S35 BT.

A Lodge Pole Pine 6" dia. bears N 36°W 20.3 ft. marked CNNW 1/64 S35 BT.



Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey contract No. 53-04R3-2-01275.

Post 5'+ South w/54-2

Post 5'+ West w/54-2 & 54-9

20° E Declination, Steel Tape

Corner falls at base of slpe South edge of tailings 200'+ from Granite Creek (South)

September 21, 1983

Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Refer to Grant County Survey No. 828

Office of... SURVEYOR ... County of... GRANT ...
 State of... OREGON ... I hereby certify that the within instrument was filed in this office
 for record on the 30 day of AUG ... 19 84
Robert D. Bayne by _____
 (COUNTY OFFICIAL) (DEPUTY)

