


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Found unrecorded pin

14.5 ft. North  
8.4 ft. East

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 25" in. ground with raised mound of stone marked:

T8S R35E

From Which:

C-S-NW-NE 1/256

A Lodge Pole 5" dia. bears N 14°W, 30.0 ft. marked X BT.

A Lodge Pole 7" dia. bears N 39°E, 8.5 ft. marked CSWNE 1/256 BT.

S35

PLS 1099

1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey contract No. 53-04R3-2-01275

Post 5'+ West w/54-2 & 54-9

Post 5'+ South w/54-2


20°E Declination Steel Tape

Corner location in tailings on North side of creek 280'+ South of road.

September 12, 1983

Witnesses: A.Ray Crapo  
Greg Orton  
Kyle McKinney

Refer to Grant County Survey No. 828



Office of SURVEYOR County of GRANT  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 30 day of AUG, 1984  
Robert D. Dwyer by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)