


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by contract no. 499 states:
Set 3 ft. by 3 ins. sq. post 24 in. in the ground for 1/4 section corner. marked 1/4 S on west face.

From which:
A Pine 7" dia. brs. N 40°W 39 lks. dist. marked 1/4 S BT.
A Pine 7" dia. brs. S 24°W 11 lks. dist. marked 1/4 S BT.




Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate distance determined by survey set a 2 1/2"x30" galvanized pipe with brass cap 12" in ground with raised mound of stone stamped:

From which:
A Lodge Pole Pine 9" dia. bears N 27°E 47.7 ft. scribed 1/4 S27 BT.
A Lodge Pole Pine 7" dia. bears S 69°W 9.8 ft. scribed 1/4 S34 BT.



Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey contract No. 53-04R3-2-01275.

Post 5'+ East w/54-9
20° Declination Steel Tape

August 29, 1983 Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Refer to Grant County Survey No. 828
Corner falls on flat area in dense Lodge Pole Pine approx. 300 ft. S. from Clearcut.

Office of... SURVEYOR ... County of... GRANT ...
State of... OREGON ... I hereby certify that the within instrument was filed in this office
for record on the... 30 day of... NOV ... 1984
Robert D. Langlitz by _____
(COUNTY OFFICIAL) (DEPUTY)

