


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate dist. determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap in ground marked:  
 From which:  
 A Lodge Pole Pine 7" dia. bears N 1°E 32.5 ft. marked  
 EW 1/64 S26 BT.  
 A Lodge Pole Pine 8" dia. bears S71°E 21.7 ft. marked  
 EW 1/64 S35 BT.

T8S R35E  
S26  
E-W 1/64 +  
S35  
PLS 1099  
1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. 53-04R3-2-01275.

Post East w/54-2 & 54-9  
Post South w/54-2

20° E. Declination Steel Tape

Corner on top of ridge 280'+ North of road.

September 22, 1983 Witnesses: A. Ray Crapo  
Greg Orton  
Kyle McKinney

Refer to Grant County Survey No. 828



Office of.....SURVEYOR..... County of.....GRANT.....  
 State of...OREGON..., I hereby certify that the within instrument was filed in this office  
 for record on the...30... day of...AUG..., 19...84...  
 ..*Robert D. Langlitz*... by .....  
 (COUNTY OFFICIAL) (DEPUTY)