


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

None



**Description of corner evidence found:**

None

**Description of monument and accessories established to perpetuate the original location of this corner:**

At proportionate position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap in ground marked:

From Which:

A Pond. Pine 10" dia. bears N 58°W 19.8 ft. marked W 1/16 S26 BT.

A Pond. Pine 10" dia. bears S 33°W 22.7 ft. marked W 1/16 S35 BT.

T8S R35E  
S26  
W 1/16—  
S35

PLS 1099  
1983

Attached brass washer stamped LS 1099 to BT blaze on both trees.


Corner location perpetuated in accordance with Umatilla N.F. survey contract No. 53-04R3-2-01275.

20° E. Declination  
Steel Tape

Post 5'+ West with 54-2 & 54-9

Corner on top of N-S Ridge edge of cut bndry. 400' above road.  
September 7, 1983

Witnesses: A. Ray Crapo  
Kyle McKinney  
Todd Olsen



Refer to Grant County Survey No. 828

Office of.....*SURVEYOR*..... County of.....*GRANT*.....  
 State of...*OREGON*... I hereby certify that the within instrument was filed in this office  
 for record on the...*30*... day of...*AUG*... 19...*84*...  
*Robert D. Bayt* by.....  
 (COUNTY OFFICIAL) (DEPUTY)