


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

W.50-20.35

History of original corner establishment:

None



Description of corner evidence found:


None

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 5/8" by 36" rebar, with a 3 1/4" aluminum cap, 30" into the bottom of small pond and 6" below the pond's surface, marked as shown, from which:

RM, 5/8" by 24" rebar with a 3 1/4" aluminum cap, set flush with the ground, S 34°02' E, 22.21 feet, stamped "RM WB2266 22.21 FT RLS 2308 1999" with an arrow pointing towards the corner.

8" Lodgepole Pine, N 86 1/4° W, 21.0 feet, scribed "WB/2266" "BT".



REGISTERED PROFESSIONAL LAND SURVEYOR

*David A. Schlaich*

OREGON  
JULY 16, 1987  
DAVID A. SCHLAICH  
2308

RENEWAL DATE: 06/30/2000

Magnetic Declination 19° East  
WORK PERFORMED BY: David A. Schlaich (RLS 2308)  
WITNESSED BY: Ray Parrish  
DATE: October 28, 1999

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 9 day of Feb, 2000  
Robert D. Beyer by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1543

W.50-20.35