

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


W-21

History of original corner establishment:

1983, Gary L. Langlitz, Registered Land Surveyor 1099, set a 2 1/2" X 30" galvanized Iron Pipe, 25" in the ground with brass cap attached (Grant Co. Map of Survey No. 828), from which:

A Western Larch 8" dia. bears S 54 1/2° W, 9.5 ft. scribed N 1/16 S35 BT

A Western Larch 22" dia. bears N 85° E, 33.7 ft. scribed N 1/16 S36 BT.




Description of corner evidence found:

Found a 2 1/2" iron pipe, with 2 1/2" brass cap, projecting 4" out of the ground, marked as shown, from which:

22" Western Larch, N 82 3/4° E, 36.7 feet with healed double blaze.

11" Western Larch, S 52 1/4° W, 9.3 feet with healed double blaze.



Description of monument and accessories I established to perpetuate the original location of this corner:

None

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David A. Schlaich*

OREGON  
JULY 16, 1987  
DAVID A. SCHLAICH  
2308

RENEWAL DATE: 06/30/2000

Magnetic Declination 19° East  
WORK PERFORMED BY: David A. Schlaich (RLS 2308)  
WITNESSED BY: Michael McVeigh  
DATE: October 7, 1999

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 9 day of Feb, +9 2000  
Robert D. Beane by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1543

W-21