


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**

Original Survey by Herman D. Gradon, in 1884, under G10 Contract No. 499 Set Post 3' long 3' sq. 24" in the ground for 1/4 Sec. Cor. From which:

- A Pine 12" dia. bears S50°E 29 lks. marked 1/4 S BT
- A Pine 10" dia. bears N11°W 60 lks. marked 1/4 S BT



**Description of corner evidence found:**

None

**Description of monument and accessories established to perpetuate the original location of this corner:**

At corner position determined by survey we set a 2 1/2"x30" aluminum pipe with aluminum cap attached set pipe 26" in the ground and stamped: From which: A Western Larch 16" dia. bears N31 1/2°W 97.4 ft. scribed 1/4 S35 BT


A Western Larch 16" dia. bears N44°E 73.5 ft. scribed 1/4 S35 BT  
Attached brass washers stamped "LS 1099" to the foot blaze of both BT's

Corner located and perpetuated in accordance with U.N.F. Survey Contract No. 53-04R3-2-275

Staff Compass 20° East Declination  
Steel Tape

Witnesses: Glen Wagoner  
Mike Wagoner  
Kyle McKinney

Refer to Grant County Survey No. 828



Office of... SURVEYOR ... County of... GRANT ...  
 State of... OREGON ... I hereby certify that the within instrument was filed in this office  
 for record on the 30 day of NOV , 19 84  
*Robert D. Beatty* by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)