

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**

Corner was established and monumented by Otis O. Gould, Surveyor, during a subdivision survey Group No. 179 dated July, 1937.

Set an iron post, 3 ft. long, 2 in. diam., 27 ins. in the ground, for cor. of secs. 5, 6, 7, and 8, with brass cap marked (as shown in the diagram)

**DIAGRAM**

T8S R36E

S 6	S 5
S 7 | S 8

from which

- A fir 12 ins. diam. brs. N21°E, (145.9') 221 lks. dist., marked T8SR36E S5 BT
- A pine 8 ins. diam. brs. S38°E, (42.2') 164 lks. dist., marked T8SR36E S8 BT
- A pine 12 ins. diam. brs. S45°W, (28.4') 43 lks. dist., marked T8SR36E S7 BT
- A pine 10 ins. diam. brs. N52 1/2°W, (64.0') 197 lks. dist., marked T8SR36E S6 BT

1937  
GLO

**Description of corner evidence found:**

2" pipe with a 2 1/2" brass cap on the west slope of a mine dump standing 10" out of the ground.

- 20" Englemann spruce (Good Condition) (Blaze Healed Over) (1937 BT) bears N22°E, 145.3 feet. Cannot see the lower portion of the BT from the corner because of the mine dump.
- 14" Lodgepole pine (Good Condition) (Scribing Visible) (1937 BT) bears S36°E, 42.7 feet.
- 16" Englemann spruce (Good Condition) (Blaze Healed Over) (1937 BT) bears S44°30'W, 29.5 feet. Tree is a spruce.
- 12" Englemann spruce (Good Condition) (Scribing Visible) (1937 BT) bears N54°W, 64.3 feet.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Maintained the monument by digging a flat spot around the monument on the mine dump slope and built a mound of rock to be 24" in diameter by 10" high around the monument.

No new bearing trees set because others are not necessary.

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to the scribed blazes which were painted red. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 22, 1983, I maintained the corner as herein described.

**FILED**

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 16 DAY OF OCT, 1985

*Robert D. Bagg Co. Sur.*

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Leland Lee Myers*

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699