

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM

Corner was established and monumented by Otis O. Gould, Surveyor, during a subdivision survey Group No. 179 dated July, 1937.

T8S R36E

Set an iron post, 3 ft. long, 2 in. diam., 20 ins. in the ground to bedrock, and in a mound of stone to top, for cor. of sects. 7, 8, 17, and 18, with brass cap marked (as shown in the diagram)

S 7 | S 8
S 18 | S 17

1937
GLO

from which

- A fir 10 ins. diam. brs. N40¹/₂°E, (52.8')80 lks. dist., marked T8SR36E S8 BT
- A fir 12 ins. diam. brs. S62°E, (13.2')20 lks. dist., marked T8SR36E S17 BT
- A pine 12 ins. diam. brs. S72° 45'W, (63.4')96 lks. dist., marked T8SR36E S18 BT
- A pine 8 ins. diam. brs. N50°W, (79.9')121 lks. dist., marked T8SR36E S7 BT

Description of corner evidence found:

2" pipe with a 2¹/₂" brass cap standing 12" out of the ground in a flattened rock mound. The limbs of the nearby Alpine fir had sweep down and nearly completely covered the monument.

- 19° Alpine fir (Good Condition)(Blaze Healed Over)(1937 BT) bears N44° 15'E, 53.9 feet.
- 14° Alpine fir (Good Condition)(Scribing Visible)(1937 BT) bears S64°E, 13.4 feet.
- 18° Ponderosa pine (16' Broken Stub)(Blaze Healed Over)(1937 BT) bears S72°W, 63.2 feet.
- 15° Lodgepole pine (8' Broken Stub)(Scribing Visible)(1937 BT) bears N50°W, 80.8 feet.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained the monument by clearing away all the brush and limbs and by improving the mound with rock to be 24" in diameter by 12" high around the monument, from which new BTs are:

- 12° Lodgepole pine bears N34°W, 48.1 feet scribed T8SR36E S7 BT
- 9° Alpine fir bears S45° 45'W, 23.9 feet scribed T8SR36E S18 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to the scribed blazes which were painted red. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 6, 1985, I maintained the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR
THIS 16 DAY OF Oct, 1985
Robert D. Pagett Co. Sur.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland Lee Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699