


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

A-17

History of original corner establishment:

Original Survey by Herman D. Gradon, in 1884, under Glo Contract No. 499
Set Post 4 ft. long 4" sqr. 24" in the ground for Corner to Section 2 & 3 from which:

- A Pine 9" dia. bears S29°E 12 lks. dist. marked
T9S R35E S2 BT
- A Tamarack 5" dia. bears S62°W 28 lks. dist marked
T9S R35E S3 BT



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At corner position determined by survey we set a 2½"x30" galvanized iron pipe with brass cap attached 24" in the ground stamped:
From which: A Spruce 14" dia. bears S35°W 36.4 ft.
scribed T9S R35E S3 BT
A Spruce 12" dia. bears S36°E 127.5 ft. scribed
T9S R35E S2 BT

T8S
S3 S2
T9S R35E
PLS 1099
1983

Attached brass washers stamped "LS 1099" to foot blaze of both BT's


Corner position located and perpetuated in accordance with Umatilla N.F. Survey Contract No. 53-04R3-2-01275

Staff Compass 20° East Declination
Steel Tape

August 3, 1983

Witnesses: Glen Wagoner
Mike Wagoner
Kyle McKinney

Refer to Grant County Survey No. 828



Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 30 day of Aug, 1984
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)