


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Found unrecorded Pin
5.7 ft. North
6.6 ft. East

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate dist. determined by survey set a brass plaque in concrete marked:
From which: T8S R35E

A Lodge Pole Pine 6" dia. bears S 15°W, 45.5 ft. marked
E 1/16 S2 BT.
A Lodge Pole Pine 6" dia. bears S65°E, 107.0 ft. marked
E 1/16 S2 BT.

E 1/16
S2
T9S
PLS 1099
1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accordance with Umatilla N.F. survey contract No. 53-04R3-2-01275.


Post 5'+ South w/54-2 & 54-9
Post 5'+ West w/54-2

20° E Declination
Steel Tape

Corner falls on Rock cliff at edge of timber cut.

September 26, 1983

Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney



Refer to Grant County Survey No. 828

Office of.....SURVEYOR..... County of.....GRANT.....
State of.....OREGON..... I hereby certify that the within instrument was filed in this office
for record on the.....30..... day of.....AUG....., 1984
.....[Signature]..... by.....
(COUNTY OFFICIAL) (DEPUTY)