


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Herman D. Gradon under G.L.O. contract No. 499 dated March 11, 1884.

Surveyor General record's state:

Set a basalt stone 12 X 12 X 10 ins 8" in ground for cor to secs 1 and 2 marked with 1 notch on the E and 5 notches on the W edges and raised a mound of stone along side.



Description of corner evidence found:


None: Corner has been destroyed by dredging operations.

(Found a 5/8" X 30" rebar 0.61 feet west of re-established corner position determined by recorded G.L.O. dist of 7.54 chains and on the south line of the SW quarter section 36 T 8 S R 35 E.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ in brass cap on a 2 inch iron pipe 27 ins, in the ground with a 6 foot steel fence post along side with a sign 54-4 attached.

Brass cap marked thus: T 8 S R 35 E



T 9 S

1979

ORLS 1639

New bearing trees:

A pine 6 ins diam bears S 52° W, 92.4 ft dist marked T 9 S R 35 E S 2 BT  
No trees available within limits in section 1.

This BT has a sign 54-3 attached below a 6 inch band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that this monument was properly re-established on June 13, 1979 witnessed by Tracy Labarce and Tom Fisk.

Office of County Surveyor County of Baker GRANT  
Oregon  
 State of Oregon, I hereby certify that the within instrument was filed in this office  
 for record on the 13 day of July, 1979  
Robert D. Baggett by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)

<b>REGISTERED PROFESSIONAL LAND SURVEYOR</b>
--

*William L. Hanley*

<b>OREGON</b> JULY 14, 1978 WILLIAM L. HANLEY 1639
---

Form R6-7100-57 (9/71) *CORNER HAS BEEN RE-VISITED SEE RE-MON SHEET FILED Aug 2, 1979*