


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established this survey by single proportionate distance between NE & NW corners of sec 1 T 9 S R 35 E and on the S line of the SE quarter sec 36 T 8 S R 35 E.



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins in the ground with a 6 ft steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus: T 8 S R 35 E

$\frac{1}{4}$ S 1
 T 9 S

1979
ORLS 1639

New bearing trees:

A pine 6 ins diam bears S 54° E, 17.9 ft dist mkd 1/4 S 1 BT
A pine 6 ins diam bears S 80° W, 71.0 ft dist mkd X BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that the above monument was established as herein described on June 13, 1979 witnessed by Tracy Labaree and Tom Fisk.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

William L. Hanley

OREGON
 JULY 14, 1978
 WILLIAM L. HANLEY
 1639

Office of..County..Surveyor..... County of...Grant.....
 State of...Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the...2nd... day of...August....., 1979
Robert D. Lopez by
 (COUNTY OFFICIAL) (DEPUTY)