


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None: Corner established this survey!



Description of corner evidence found:


None

*VOID superseded by filed 8/2/79 revised re-mon sheet*

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ in brass cap on a 2 inch iron pipe 31 ins long, 28 ins in the ground with a 6 ft steel fence post along side with a sign 54-9 attached.

Brass cap marked thus: T 9 S R 35 E



1979

ORLS 1639

New bearing trees:

- A pine 6 ins diam bears S 01° E, 97.5 ft dist marked N 1/16 S 1 BT
- A pine 6 ins diam bears S 50° W, 39.6 ft dist marked N 1/16 S 1 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that this monument was properly established on June 12, 1979, witnessed by Tracy Labaree and Tom Fisk.

Office of.....County...Surveyor..... County of...Grant.....  
 State of...Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the 13 day of July, 1979  
*Robert D. Baggett*  
 (COUNTY OFFICIAL) (DEPUTY)

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*William L. Hanley*

---

**OREGON**  
 JULY 14, 1978  
 WILLIAM L. HANLEY  
 1639