


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None: corner established this survey.




Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long, 28 ins in the ground with a 6 ft steel fence post alongside with signs 54-9 and 54-2 attached.

Brass cap marked thus: T 9 S R 35 E



1979
ORLS 1639

New bearing trees:

A pine 6 ins diam bears S 01° E, 97.5 ft dist marked CN 1/16 S 1 BT
A pine 6 ins diam bears S 50° W, 39.6 ft dist marked CN 1/16 S 1 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that this monument was properly established on June 12, 1979 witnessed by Tracy Labaree and Tom Fisk.

Office of County Surveyor County of Grant
 State of Oregon I hereby certify that the within instrument was filed in this office
 for record on the 2nd day of August, 1979
Albert D. Baggett by _____
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639