


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None: Corner established this survey.



Description of corner evidence found:

None

*VOID
Superseded by revised remon sheet
filed 8/2/79*

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long, 26 ins in the ground with a 6 ft steel fence post along side with a sign 54-9 attached.

Brass cap marked thus: T 9 S R 35 E

NE $\frac{1}{16}$ S 1

1979

CRLS 1659

New bearing trees:

A tamarack 14 ins diam bears S 75° W, 51.5 ft dist mkd NE 1/16 S 1 BT

This BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that this monument was properly established on June 12, 1979, witnessed by Tracy Labaree and Tom Fisk.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

William L. Hanley

**OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639**

Office of..... County Surveyor..... Grant..... County of.....
State of...Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...13 day of...July....., 19...79
.....*Robert D. Baggett* by.....
(COUNTY OFFICIAL) (DEPUTY)