


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None: corner established this survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long, 26 ins in the ground with a 6 ft steel fence post alongside with a sign 54-9 attached.

Brass cap marked thus: T 9 S R 35 E

NE $\frac{1}{16}$ | S 1

1979
ORLS 1639

New bearing trees:

A tamarack 14 ins diam bears S 73° W, 51.5 ft dist mkd NE 1/16 S 1 BT
A pine 06 ins diam bears S 08° E, 58.5 ft dist mkd NE 1/16 S 1 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that this monument was properly established on June 12, 1979 witnessed by Tracy Labaree and Tom Fisk.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

Office of..... County Surveyor..... County of... Grant.....
State of... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 2nd day of... August....., 1979
Robert W. Boyer by.....
(COUNTY OFFICIAL) (DEPUTY)