

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by Herman L. Gradon under G.L.O. contract No. 499 dated March 11, 1884.

Surveyor General records state:

Set post 3 ft long 3 ins square 24 ins in ground for 1/4 sec cor marked 1/4 S on W face from which:

A pine 7 ins diam bears N 25° E, 9 lks dist mkd 1/4 S LT  
 A pine 8 ins diam bears N 62° W, 6 lks dist mkd 1/4 S BT



Description of corner evidence found:

None: Corner re-established by single proportionate distance.

*Handwritten:*  
~~VOID~~  
 superseded by revised return  
 sheet filed 8/2/79  
 OK

Description of monument and accessories established to perpetuate the original location of this corner:


Set a 2 1/2 inch brass cap on 2 inch iron pipe 31 ins long, 26 ins in the ground with a 6 ft steel fence post with signs 54-2 and 54-4 attached.

New bearing trees:

A pine 6 ins diam bears N 62° W, 27.3 ft dist mkd 1/4 S 2 BT  
 A pine 8 ins diam bears S 67° E, 29.5 ft dist mkd 1/4 S 1 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

Brass cap marked thus: T 9 S R 35 E



1979  
 ORLS 1639

**REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR**

*William L. Hanley*

**OREGON**  
 JULY 14, 1978  
 WILLIAM L. HANLEY  
 1639

I hereby certify that this monument was properly re-established as herein described on June 8, 1979, witnessed by Tracy Labaree.

Office of.....County Surveyor..... County of.....Grant.....  
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the.....13 day of.....July....., 19.....79  
*Robert D. [Signature]* by.....  
 (COUNTY OFFICIAL) (DEPUTY)