


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None: corner established this survey.




Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long, 26 ins in the ground with a 6 ft steel fence post alongside with a sign 54-9 and 2 signs 54-2 attached.

Brass cap marked thus: T 9 S R 35 E



New bearing trees:

A tamarack 8 ins diam bears N 28° E, 19.8 ft dist mkd CW 1/16 S 1 BT
A pine 6 ins diam bears S 80° E, 45.1 ft dist mkd CW 1/16 S 1 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify the above corner monument was properly established on June 12, 1979 witnessed by Tracy Labaree and Tom Fisk.

Office of... County Surveyor..... County of... Grant.....
 State of... Oregon..... I hereby certify that the within instrument was filed in this office
 for record on the 2nd day of August, 1979
Robert D. Bayart by
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William L. Hanley

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639