CERTIFIED RECORD OF LAND CORNER MONUMENTATION

E-17

History of original corner establishment:

1884, Herman D. Gradon, U.S. Deputy Surveyor, while subdividing the township under GLO Contract No. 499 established this corner. He set a post 4' long, 4" square, 24" in the ground, from which:
9" Pine, N 55° E, 16 links.
5" Pine, S 25° E, 87 links.
40" Pine, S 71° W, 18 links.
6" Pine, N 10° W, 26 links.

1898 – 1909, The corner was found and tied by Mineral Surveys 358, 368, 637, 650A&B, and 721.

1983, Gary L. Langlitz, Registered Land Surveyor 1099, found the SW and NW BT's and set at record bearing and distance, a 2 1/2" by 30" galvanized pipe, with brass cap, 24" in the ground with a mound of dirt and stone to cap (Grant Co. Map of Survey No. 828), from which:
12" Lodgepole Pine stump & snag, N 10° W, 17.2 feet, with scribing visible.
30" rotted Ponderosa Pine stump, S 71° W, 11.9 feet, with scribing visible.
Marked New BT's:
8" Douglas Fir, N 56° W, 105.5 feet.
10" Ponderosa Pine, N 85° E, 36.1 feet.
8" Lodgepole Pine, S 23 1/2° E, 10.4 feet.
6" White Fir, S 85° W, 39.4 feet.

1997, David A. Schlaich, Registerd Land Surveyor 2308, found a 2 1/2" iron pipe, with a 2 1/2" brass cap, projecting 7" out of the ground (Grant Co. Map of Survey No. 1454), from which:
13" Ponderosa Pine, N 88 1/2° E, 36.1 feet. with scribing visible on partially healed double blaze.
10" Lodgepole Pine, S 21° E, 10.4 feet, with scribing visible on partially healed double blaze.
12" White Fir, S 87 1/2° W, 39.4 feet, with scribing visible on partially healed double blaze.
11" Douglas Fir, N 53 1/4° W, 105.5 feet, with scribing visible on partially healed double blaze, with a 1 1/4" brass washer stamped "LS 1099" nailed to the lower blaze.
Stump hole, N 10° W, 17.2 feet.

1998, Douglas M. Ferguson, Registered Land Surveyor 848, found and tied the corner while performing a R–O–W Survey for Grant County (Grant Co. Map of Survey No. 1463).

DIAGRAM

T9S R35E

S 3	S 2
S10	S11

Description of corner evidence found:

Found a 2 1/2" iron pipe, with a 2 1/2" brass cap, projecting 7" out of the ground, marked as shown, from which:

14" Ponderosa Pine, N 88 1/2° E, 36.1 feet, with scribing visible on almost completely healed double blaze and 1 1/4" brass washer stamped "LS 1099" nailed to the lower blaze.
10" Lodgepole Pine, S 21° E, 10.4 feet, with scribing "9SR35ES4" "BT" visible on a partially healed double blaze and a 1 1/4" brass washer stamped "LS 1099" nailed to the lower blaze.
Stump hole, S 71° W, 11.9 feet (original BT).
12" White Fir, S. 87 1/2° W, 39.4 feet, with scribing visible on almost completely healed double blaze.
11" Douglas Fir, N 53 1/4° W, 105.5 feet, with scribing "T9SR35ES3" "BT" visible on a partially healed double blaze and a 1 1/4" brass washer stamped "LS 1099" nailed to the lower blaze.
Stump hole, N 10° W, 17.2 feet (original BT).

T9S R35E
S 3 | S 2
S10 | S11
PLS 1099
1982

Description of monument and accessories I established to perpetuate the original location of this corner:

None

Magnetic Declination 19° East
WORK PERFORMED BY: David A. Schlaich (RLS 2308)
DATE: September, 1999

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A. Schlaich

OREGON
JULY 16, 1987
DAVID A. SCHLAICH
2308

RENEWAL DATE: 06/30/2000

Office of SURVEYOR *County of* GRANT
State of OREGON, *I hereby certify that the within instrument was filed in this office for record on the* 3 *day of* NOV. *19* 99
Janet D. Bayett *by*
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1534

E-17