



R 31 E

NOTE

1. The G.L.O. survey of T18S, R31E was done by Reuben R. Leigh under contract no. 462 dated April 11, 1883.
2. The G.L.O. survey of T19S, R31E was done by Henry W. Cooke under contracts no. 470 dated April 14, 1883 and no. 494 dated January 16, 1884.
3. The north and east boundaries of Section 21 was monumented and posted as the USFS boundary by David Armstrong P.L.S. 1026 and filed December 23, 1983 as Grant Survey no. 795.

LEGEND

- Found 2" dia. galvanized iron with a 2-1/2" brass cap set by Sherman Anderson, P.L.S. 1067 in 1978.
- G.L.O. corners found and monumented with 2-1/2" dia X 30" long aluminum pipe with a 3-1/4" aluminum cap.
- Forest Boundary posted per U.S.D.A., Malheur National Forest purchase order.

RECORDATION

Office of County Surveyor, County of Grant, State of Oregon. I hereby certify that the within instrument was filed for record on the 18 day of June 1987.

Survey no. 1002

Robert D. Bayard
Grant County Surveyor

Office of County Surveyor, County of Harney, State of Oregon. I hereby certify that the within instrument was filed for record on the 24 day of June 1987.

Survey no. 355

Chris T. Palmer
Harney County Surveyor

REGISTERED PROFESSIONAL LAND SURVEYOR <i>Chris T. Palmer</i> OREGON SEPTEMBER 23, 1977 CHRIS T. PALMER 1288	SNOW MOUNTAIN PINE CO. HINES, OR		
	SURVEY PLAT		
	A PORTION OF T18S, R31E, WM, GRANT CO., OR. A PORTION OF T19S, R31E, WM, HARNEY CO., OR.		
	Scale: 1"=1000'	Date: MAY 1987	Job: 1039
Dsn:	M. A. Palmer & Sons ENGINEERING & SURVEYING 254 N. Alder - Box 61 Burns, Oregon 97720		Sht. No. 1
Dm: CTP			
Ckd:			of 1