



BASIS OF BEARINGS
Map of Survey No. 1167

- LEGEND**
- Found 1-1/2" iron pipe with attached Grant County Surveyor Brass Cap monument.
 - Found 5/8" iron pin with attached Aluminum Cap, marked BGA SURVEY MARKER.
 - Set 5/8"x 30" iron pin with attached aluminum cap marked BGA SURVEY MARKER.
 - x—x Fence line.
 - Found monument from Recorded Survey No. □ Survey No. appears in the box.

NARRATIVE: This survey was performed at the request of Jim Walker, Assistant County Road Supervisor. The purpose of this survey was to partially reconfigure the boundary lines of the a crushed rock storage site, as shown on Map of Survey No. 1200. Also, as requested, we delineated a new rock quarry site, as shown hereon.

A search was made of the available records pertaining to this survey. Field measurements were made to locate appurtenant existing monuments from Survey No. 1200 and right of way monuments along County Road No. 54, at the rock storage site. New monuments were set at locations approved by Mr. Walker and the land owner, Holliday Family Ranches.

I found no deeded right of way for the county road along the east side of the rock quarry site.

REFERENCES

Deed Record Book 127 Page 548-557
Instrument No. 910655, 920418
Record Map of Survey No. 502, 1167, 1200
Plat of Pine Creek Park Subdivision.

NOTES:
We drove 6 ft. long galvanized steel fence posts alongside each pin set, where practical.

The section and section subdivisional lines shown are protracted for general information only.

RECEIVED AND FILED
July 14, 1992
OFFICE OF COUNTY SURVEYOR
Robert D. Baggett
ATTEST: J.L.W.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
JULY 12, 1983
ROBERT D. BAGGETT
598

BAGETT - GRIFFITH & ASSOCIATES John Day, Oregon	
MAP OF SURVEY OF PROPOSED LEASE FOR ROCK QUARRY AND GRAVEL STORAGE SITE SITUATED IN THE NW1/4 AND IN THE N1/2SW1/4 SEC. 36 T13S, R32E, W.M.	
GRANT COUNTY, OREGON	
SURVEYED FOR	GRANT COUNTY ROAD DEPARTMENT
SURVEYED BY	RDB & SDF & NF 5/7/92
Scale: 1"=200'	Drawn by: J.L.W.