



Scale 1"=500'

## BASIS OF BEARINGS

SOLAR OBSERVATION Taken near S1/4 Section 28

## **LEGEND**

- Found 1½" iron pipe with attached 2" brass cap See Survey No. 7G.
- Set 2½" aluminum pipe with attached 2½" aluminum cap.

x---x Fence Line

Record bearing and distance.


## NARRATIVE

This survey was performed at the request of Wayne Howard. The purpose of this survey was to establish the C1/4 corner of Section 32, and flag the property lines for fencing..

After searching the available records pertaining to this survey, I found that the controlling corners of Section 28 were remonumented by Vernon Glaze in 1914, see survey number 7G. I found all the controlling corners of Section 28 with the exception of the S1/4 corner. The S1/4 corner was set at single proportion between the SW and the SE corners of Section 28. The C1/4 corner was established at the intersection of the center of section lines.

RECEIVED AND FILED

JUL 1 5 1990





## CORNERSTONE SURVEYING, Inc.

233 S. Canyon Blvd., John Day, Oregon (541) 575—1813

MAP OF SURVEY DEPENDANT RESURVEY AND SUBDIVISION OF SECTION 28, T12S, R28E, W.M.

GRANT COUNTY, OREGON

Date: 6/5/98

SURVEYED FOR: Wayne Howard

SURVEYED BY : Jack Watson

DRAWN BY: Jack Watson